

Component Update - NTA5318 Back Leak Adaptor Change Update TSN012

Due to the availability of parts related to difficulties within our supply chain, the Part contained in NTA5318 has now been changed. A temporary measure was put in place in June 2022 as confirmed in TSN010.

This change has now become permanent as of July 2022

Please circulate to all Technical Distributors


Affected Kits:

- HK1225
- HK1225/C
- HK1178
- HK1178/C



Fitting Back Leak Adaptor:

The following process details the correct installation of the New NTA5318 Backleak Adaptor:





[Click here to view this document in the Technical Help Centre](#)

If you have any questions or queries, please contact the Hartridge Technical Support Team or your Hartridge Territory Manager.

Hartridge Ltd, The Hartridge Building, Network 421 Radclive Road, Buckingham MK18 4FD, UK
Tel: +44 (0)1280 830010 Fax: +44 (0)1280 825 601 support@hartridge.com

Technical Support Note TSN012 v1, 21.07.2022